DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-000722 Address: 333 Burma Road **Date Inspected:** 24-Oct-2007

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 1400 **OSM Departure Time:** 2300 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes No Zhu Zhonghai **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

34-0006 **Bridge No: Component:** 89 Meter Mock-Up

Summary of Items Observed:

The Caltrans Quality Assurance (QA) Inspector Roscoe Dixon arrived on site at the Zhenhua Port Machinery Company (ZPMC) facility at Changxing Island, in Shanghai, China to periodically monitor welding and Quality Control (QC) functions. While on site the QA Inspector observed and/or discovered the following. This QA Inspector, Roscoe Dixon randomly observed ZPMC personnel carbon air arc gouging of the 89 Meter Mock-Up longitudinal plate stiffeners identified as piece marks mp534-C1, mp535-A1 and mp538-A1. The QA Inspector also witnessed the in process welding of two lifting lugs onto the 89 Meter Mock-Up Skin E piece mark mp502-1. The ZPMC Certified Welding Inspector (CWI) Zhu Zhonghai informed the QA Inspector the approved welding procedure specification WPS-13-P-2112 was being followed to perform the welding. The ZPMC approved qualified welder Han Xiaofeng ID # 05446 was utilizing Shielded Metal Arc Welding (SMAW) process 5.0mm diameter electrode designated as E7018. This QA Inspector observed the ZPMC Quality Control (QC) personnel An Qingxiang Chin check the welding machine amperes at 210 and 27 volts using a voltage meter, This QA Inspector Dixon also performed random verification of the weld parameters using a Fluke meter. This QA Inspector visually verified the above listed approved WPS, which was posted near the welding operation and determined that the welding and work being performed on the items listed above appeared to comply with WPS and the contract documents. See photographs below to provide additional detail.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)





Summary of Conversations:

As noted above and basic communication between QC Inspector and QA inspector when and where welding inspections are to be performed.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Dixon,Roscoe	Quality Assurance Inspector
Reviewed By:	Cochran,Jim	QA Reviewer